

Nacrtať na formátu A3 položaj tolerančných polí a diagrame zozoru i preklopa za familije sklopova:

	A		B	
1	H7/g6, h6, z8	d=20 mm	h8/D9, P8, X9	d=48 mm
2	H6/e6, m6, u7	d=25 mm	h8/D7, D8, V9	d=44 mm
3	H5/c6, j6, t5	d=30 mm	h8/E7, P8, X8	d=40 mm
4	H7/g7, h8, z6	d=35 mm	h8/F7, R8, S9	d=36 mm
5	H7/g7, h8, z7	d=40 mm	h8/G7, S8, Y7	d=32 mm
6	H8/d7, j8, v9	d=45 mm	h7/G6, H6, Z8	d=28 mm
7	H8/e7, p8, x8	d=50 mm	h6/E6, M6, U7	d=24 mm
8	H8/f7, r8, s9	d=55 mm	h9/A8, K10, X8	d=62 mm
9	H8/g7, s8, y7	d=60 mm	h8/B8, J8, V7	d=64 mm
10	H9/b8, j9, v8	d=65 mm	h9/C9, M8, Z8	d=66 mm
11	H9/c8, m8, z9	d=70 mm	h7/F6, K8, S7	d=68 mm
12	H9/c8, m8, z10	d=75 mm	h8/F7, R8, S9	d=35 mm
13	H7/f8, k9, s6	d=80 mm	h8/E7, P7, X8	d=42 mm
14	H7/d9, n6, r6	d=85 mm	h8/D7, J8, V7	d=49 mm
15	H10/a10, k9, x9	d=90 mm	h7/G7, H8, Z7	d=56 mm
16	H10/b10, m9, v9	d=124 mm	h8/E7, P7, X8	d=42 mm
17	H11/c10, p9, z10	d=185 mm	h8/D7, J8, V7	d=36 mm
18	H9/a8, k10, x8	d=82 mm	h7/G7, H8, Z7	d=32 mm
19	H8/b8, j8, v7	d=72 mm	h7/F6, H7, X6	d=28 mm
20	H9/c9, m8, z8	d=68 mm	h5/C4, J5, S4	d=16 mm
21	H7/f6, k8, s7	d=56 mm	h6/E5, M6, U5	d=12 mm
22	H8/f7, r8, s9	d=48 mm	h7/G7, H6, Z7	d=45 mm
23	H8/e7, p7, x8	d=42 mm	h9/C8, M8, Z10	d=75 mm
24	H8/d7, j8, v7	d=36 mm	h7/F8, K9, S6	d=80 mm
25	H7/g7, h8, z7	d=32 mm	h7/D9, N6, R6	d=85 mm
26	H7/f6, h7, x6	d=28 mm	h10/A10, K9, X9	d=90 mm
27	H5/c4, j5, s4	d=16 mm	h10/B10, M9, V9	d=124 mm
28	H6/e5, m6, u5	d=12 mm	h11/C10, P9, Z10	d=185 mm
29	H7/g7, h6, z7	d=45 mm	h9/A8, K10, X8	d=82 mm
30	H8/f7, r8, s7	d=55 mm	h7/D8, N6, R6	d=85 mm